

DIGITAL TORQUE METER **TNX** SERIES

Instruction Manual

Please read the following content before operation

Please read instruction manual and [safty notes]carefully before operation,the operate correctly.

Safety notes

please comply

Please read instruction manual carefully before installation , operation, maintenance, check, read , product knowledge, safety information, not before operation.

[Danger], [warning], [caution] differentiate the importance of safety notes in the instruction manual, they are very important. Please comply.



Danger mark indicates a possible death, serious injury or fire if the user disregards the instruction .



Warning mark indicates the possibility of a serious injury if the user does not follow the instruction .



Caution mark indicates the possibility of light injury or dangers if user operates improperly . And that lead to great effect base on different instance. please comply.

The following marks indicate the sort of contents which are complied with.



The mark indicates warning, please pay attention .



The mark indicates prohibit operation.



The mark indicates follow instruction.







Warning















Heavy! Pay close attention to operation

When the product falls on user foot ,it leads to serious injury .
 ✘ Please refer to P25 about the weight of product.

Caution

| | |
|--|--|
|  <p>Don't exceed the bound of torque moment. While exceeded the bound of torque moment ,the inductor and other parts may go wrong .</p> |  <p>Please place the product on the convenient . location when maintenance and check.</p> |
|  <p>Do not more and hold the product while . The power is on while power cables break off,it may lead to electric shock,fire,injury.</p> |  <p>Please check it the object is fix up. Please check the object is fix up not to more. The object cannot be test correctly while it can move.</p> |
|  <p>Please check the electric source is single phase . The voltage of electrical outlet is equal to the mark voltage.Don't connects many power cables. while power cable break off,it may lead to electric shock ,fire,injury.</p> |  <p>Do not mangle ,bend ,pull , turn, twist power cables. Don't place object on the cables .Don't nip power cables. while power cable breakoff,it may lead to electric shock,fire,injury.</p> |

⚠ Caution

| | |
|--|---|
|  <p>Don't charge with other instruction except AC connect instruction ,it may leads to circuit damage and fire.</p> |  <p>Don't use except AC 100v It may lead to fire and electrical shock fire .</p> |
|  <p>Please insert power cable. into AC connet instrument while use in the loose condition,it may lead to electric shock and fire for short circuit.</p> |  <p>Don't plug into or unplug from AC connect instrument. it may leads to electric shock.</p> |
|  <p>Don't disconnect .repair ,alter. It may lead to injury for improperty operation.</p> |  <p>Don't haul AC connect instrument . If soft cable break off,it may lead to fire,forshort circuit.</p> |
|  <p>Don't use while AC connect instrument touch with dust it may lead to fire.</p> |  <p>Don't use and save in the following enviroment:dank, sunniness,corrsive air,flammable air.</p> <ul style="list-style-type: none"> • The environmental which requires water, the place where direct sunlights hit • Environment which condensation generates • Environment with much dust, salt, and iron • Environmental which requires oil, water, and chemicals • A place with corrosive gas and combustibile gas |
|  <p>Please wipe with the clean .Soft cloth while it is dirty.Don't use gas ,thinner,ethanet.</p> |  <p>Use it the temperature bound(0 ~ 40°C) It may lead to wrong operation if exceed the temperature bound.</p> |
|  <p>Suggest examination and adjustment at times. The test definition will drop together with time according to the use frequency and torque.</p> |  <p>Use in the humidity bound(35 ~ 85%RH) (Not mirage).It may lead to wrong operation if exceed the humidity.</p> |


INDEX

| | | |
|--|---|---|
| 1. <u>Characteristic of this product</u> 3 | 8. <u>Graduat function</u> 8 | 13.2 <u>Characteristic of digitorq_TNX</u> 20 |
| 2. <u>Confirm the appendant</u> 3 | 8.1. <u>Record graduation</u> 8 | 13.3 <u>loaddown sequence of digitorq_TNX</u> 20 |
| 3. <u>Name and function of each part</u> 3 | 8.2. <u>Express graduation</u> 9 | <u>13.4 notes in USB operation</u> 20 |
| 3.1. <u>Mainframe</u> 3 | 8.3. <u>Canel graduation</u> 11 | 14. <u>Convient function</u> 21 |
| 3.2. <u>Operational panel</u> 4 | 8.4. <u>Canel all data</u> 11 | 14.1 <u>Set the loading of storage outside</u> 21 |
| 3.3. <u>LCD display part</u> 4 | 9. <u>Save USB graduation(all graduat data)</u> 12 | <u>14.2 Warning code in setting parameter</u> 21 |
| 3.3.1. <u>Value display part</u> 4 | 9.1 <u>Method for saving USB graduation</u> 12 | 15. <u>set the operation of time</u> 22 |
| 3.3.2. <u>Unit display part</u> 5 | 9.2 <u>Warning code in USB graduation saving</u> 12 | 16. <u>Connect instrument outside</u> 23 |
| 3.3.3. <u>Charge display part</u> 5 | 9.3 <u>Format of data file</u> 13 | 16.1 <u>Pin eith lock</u> 23 |
| 4. <u>Summary of keyboard</u> 5 | 10. <u>Copy output</u> 14 | <u>16.2 Overload output/compare instrum output</u> 23 |
| 4.1. <u>Basal key operation</u> 5 | 10.1 <u>Method for copying statist data</u> 14 | 17. <u>Charge</u> 24 |
| 4.2. <u>Pecial key operation</u> 5 | 10.2 <u>Example and format of print</u> 14 | 18. <u>Technolgy supporting</u> 24 |
| 5. <u>Method of tes</u> 5 | 11. <u>Set function</u> 15 | 18.1 <u>About repairment and rectfy</u> 24 |
| 5.1. <u>Method of open test</u> 6 | 11.1 <u>Types of function</u> 15 | <u>18.2 Guarantce</u> 24 |
| 5.2. <u>Method of close test</u> 6 | 11.2 <u>Method of operation</u> 15 | 19. <u>Type</u> 25 |
| 5.3. <u>Method of average test</u> 6 | 12. <u>Set daterminant upper</u> 18 | 20. <u>Rule grap</u> 25 |
| 6. <u>Function of compare instrument</u> 7 | 12.1 <u>Set operating of determiant upper</u> 18 | |
| 7. <u>Method of test</u> 7 | 12.2 <u>Output of determinant result of compare instrument</u> 19 | |
| 7.1. <u>Fixing of test sample</u> 7 | | |
| 7.2. <u>0 point adjustment</u> 7 | 13. <u>The adoption of data</u> 20 | |
| 7.3. <u>Determine</u> 7 | 13.1 <u>Function of USB communication</u> 20 | |

1.Characteristic of this product


- Because it suit for P.P,so you can land save function 1st ,2nd ,3rd ,close,each of which are 1000 details.
- Can test the torque of open.close direction.
- Can save graduate land value to USB storage.
- Because of USB communication, it can send data into computer .
- Connect to the printer(buy besides),you can print save data.
- Can shift overload output/compare instrum output
- Because it is suitable for spare electric.
- Tsrque(DSP_10),you can use it as electric tsrque test.
- Record data,time of open/close Max value recorded through clock funtion.
- Can test MAX value
- Prove fix torque of instruction 2N.m,5N.m,10N.m.
- Can shift each unit of N.m,N.m.
- Can chose test cycle(inclicate cycle)from 8t/s,4t/s,2t/s,1t/s.

2.Confirm the accessory




3.Name and funtion of each part

3.1 Mainframe




| | |
|----------------------------------|---|
| Test table | put test sample |
| Operation panel | 各種キー、LED が配置されています。 |
| Special socket for USB storge | USB メモリを差し込みます。(注)PC との通信には使用できません。 |
| Fix open handle | チャックピンを開閉させる際に使用します。 |
| Fix bolt | サンプルを固定する際に使用します。 |
| Socket for AC connect instrument | AC アダプタで動作させる際に使用します。 |
| Connect socket outside | Use when connect spare electric torque or print(use when exceed output/compare instrument output) |
| Socket for USB communication | Use when PC is communicating with USB. |

3.2 Operation panel



| | |
|---|---|
| ① POWER KEY | Use for ON/OFF the power |
| ② RECALL KEY | Load the data inputed in storage when open/close the test. Can't load the data inputed in storage shen in overage testing. |
| ③ MEM KEY | Input max value into storage when open/close the test .Can't save input when in average testing. |
| ④ Open/Close KEY | Shift test method Keep pressing the button will return to the method. |
| ⑤ FILE KEY | When it is open/close test method :save store data of mainframe into USB storage Store data indicates:input store data of mainframe to printer . ((only when F06=print |
| ⑥ ZERO/RST KEY | When avverage test: set zero.Method of open/close test : resert max value |
| ⑦ Lcd indicate part | Indicate test data or test unit . |
| ⑧ Test indicate LED | One of open ,Mean,Close light, then indicate test method. |
| ⑨ Compare test determination indicate LED | When campare test determination is effective ,one of Hi,Go,Lo is light then indicates determinant result. Method of average test: against test data to do determinant of compare test and indicate result. Method of open/close test :against max value to do determinant of compare test and indicates result. When store exprossing ,against store value to do determinant of compare test and indicate result. Hi,Go,Lo isn't light when determinant of compare test doesn't work. |

3.3 LCD indicate part



3.3.1 Value indicate part


Indicat the test value with symbol and 4 states value.

The symbols of torque are different according to the difference of test method .

| Test method | Torque of open direction | Torque of close direction |
|---------------------|--------------------------|---------------------------|
| Open test method | No symbol | Indicate negative |
| Close test method | Indicate | No symbol |
| Average test method | No symbol | Indicate negative |


3.3.2 Express unit

Express unit . Indicate "OVR" when exceed load Indicat "PWR" one minute before turn off the power .




3.3.3 Charging display

Indicate flowing contents accrding to charge state.



LO BAT Blinking :
The internal nickel metal hydride batteries voltages is declinling.
Please connect AC suitable instrument to charge.



BAT At display:
A internal nickel metal hydride batteries is under charge.
Even shut off the power,indicates "BAT" when charging.

4.Summary of key operation.

4.1 Operation of basic operation.


| Names of keys | Operation |
|---------------|----------------------------------|
| POWER | ON/OFF of power |
| Open/Close | Transfer test method |
| FILE | Save data into USB panel/printer |
| ZERO/RST | Set reset 0 /reset MAX height |
| MEM | Input data of MAXheight |
| RECALL | Indicate after record data |

4.2 A special key the operation

| Operation key | Operation | Operation method |
|------------------|-------------------|---|
| ZERO/RST + POWER | Function form | When power is OFF,keep pressing ZERO/RST and power,then away. |
| MEM + POWER | Cancel store data | When power is OFF,keep pressing MEM and until indicate "non E" canceled by store data. |
| RECALL + POWER | Comparison set | When power is OFF,keep pressing recall key and power the away. Keep pressing RECALL until indicates "1-H" of comparison set. |
| FILE + POWER | Time set | When power is OFF ,keep pressing FILE and power then away. Keep pressing FILE until indicates "YEA" of time set. |

5.Test form

Test form contains open test porm,close test form,use open/close button to shift.




5.1 Open test form


Test the max torque presured on test table of open direction.

Display cycle : 8 times per second.

Resert max height point by press ZERO/RST key.



Use "-" express torque value if close driection . use out of wine of real time to express torque of max height point pressed on open direction.




5.2 Close test form


Test the max of torque pressed on close diection of test table.

Display cycle : 8 times per second.

Resert the max height point by press ZERO/RST.




Use "-" express torque value of open direction. use out of wine of real time to express torque of max height point pressed on close direction.



5.3Average test form


Indicate torque value each sample(1000t/s)of test table^{*}direction according cycle with real time torque. cycle settet accrodg to mochine funtion, add number "1"to torque of close direction(1t/s,2t/s,4t/s,8t/s) resert 0 by press ZERO/RST key.



* Set filter(F04)as 150 msec,then 150t/s.


6.Function of test instrument

- Compare determinant upper/lower limit value with test data,max or store data loaded.LED light and indicate result.
- Can set determinant upper/lower limit value of 1st,2nd,3rd separately.(reher to set operation of determinant upper/lower limit value of P12.1)
- Can't set determinant output when determinant upper limit value and determinant lower limit value are all set as 0.
- Compare determinating with absolute value not determinate upper/lower limit.
- Again st average test method,determinate upper/lower limit through real time.
- Determinate upper/lower lomit value when express store data or record max value,degree in case of about open/close test method.




■ Determinant management(determinant upper limit value:100/determinant lower limit value 50)

● when open test method




determinate LO when test data is in 0-49 (LED of "LO" light)
 determinate GO when test data is in 50-100 (LED of "GO" light)
 determinate HI when test data is in 101- (LED of "HI" light)

● when close test method



determinate LO when test data is in 0-49 (LED of "LO" light)
 determinate GO when test data is in 50-100 (LED of "GO" light)
 determinate HI when test data is in 101- (LED of "HI" light)

● average average test method



()In the inside, it is a display value.
 determinate HI when test data is in -101 (LED of "HI" light)
 determinate GO when test data is in -100-50 (LED of "GO" light)
 determinate LO when test data is in -49-49 (LED of "LO" light)
 determinate GO when test data is in 50-100 (LED of "GO" light)
 determinate HI when test data is in 101- (LED of "HI" light)

7.Measuring method


7.1 Fix test smaple

- 1 relax handle for set on off one test table
- 2 adjust the set bolt to compatible bulk and shape,then insert into any position.
- 3 put sample on the test table
- 4 close handle of set on_off and fasten the sample

※ fasten the main top of sample to the center of the table

When it is difficult for a form to bring an end caps to centers of tables with bad samples etc., please manufacture the fixture implement reserving a sample.

※ The length of a zipper pin is preparing 10mm, 20mm, and 50mm as the option.



7.2 ZERO adjustment

Turn test sample toward testing direction,it will appear torque about sample.
 So you have to keep pressing ZERO/RST key to reset before test next sample.

7.3 Please reset peak in cordition of no connection with torque.

If a measuring samples is turned in direction, the torque concerning a sample will be displayed.
 Since display maintenance of the maximum of the torque which started is carried out, in the case of opened and closed torque measurement mode, please press the ZERO/RST keys, and carry out peak reset, before measuring the following samples.



※ Please perform peaks resets in the state where torque does not start.

8.storage instrument function

8.1 1 store land


When in open/close test mode,through keep pressing MEM key to land the max value to storage open test mode

[open test mode]



If keep pressing MEM key,when load the max value in storage,reset the max height poin after 1 second.


【Close test mode】




8.2 Memory indication

Memory indicate open test mode, then press RECALL key to enter memory indication mode.
 Memory data of memory indication mode are finally indicated.

【When open 1st/close choosing】




【When open 2nd/3rd choosing】




8.3 Cancel final data

When final code, data indicating keep pressing ZERO/RST key to cancel Data of final memory code.




Keep pressing ZERO/RST key to cancel final data in condition of only one data left Then main display part "nonE" indicating for 2 second and return to test mode.



8.4 Cancel all data (all memory data)


When the power is OFF, keep pressing MEM key and power key and power key, then unclinch simultaneity. If keep pressing MEM, the memory data of open test and close test are all canceled.



9.USB memory save

9.1 Ways for saving USB memory

USB memory save is to save .Peal hold value inputed in memory and it statistical data by keep pressing FILE key when in open/close test mode. Besides,when saving in USB memory,determinating upper/lower limit by determinant upper /lower limit value setted and save the results. Accessoral USB memory of appropriative connector for USB memory on right side of mainframe close test mode.



- Record positing of storge data saved
storge data recorded by CSV form in file SHIMPO of USB storge.

root directory

+ -- SHIMPO

+ -- *****.CSV

※ When there is no SHIMPO file in USB storge,it will recorded automatically.

- File name format

Record file name of storge data according to following provision .

\$MMDD***.CSV

\$: O (open storge data)、C (close storge data)

MM : month (01 ~ 12)

DD : day (01 ~ 31)

*** : continuous number : 001 ~ 999 (As many as 999 pieces)

Code follow the max number of continuous month,day in SHIMPO file.

9.2 Noticing code saved in USB memory.

Sometimes indicate code in USB memory save.

After indicate code confirmation ,then pressing zero key to indicate clear.

| Code | Meaning | Method management |
|------|--|--|
| U-10 | No memory data save in USB memoring | Peak torque,please load memory. |
| U-11 | Don't insert into USB memory | <ul style="list-style-type: none"> • Please insert USB memory . • Please connect USB memory again. • Please connect another USB memory. |
| U-12 | No space in USB memory | <ul style="list-style-type: none"> • Please increase the capacity of USB memory |
| U-13 | Fail to visit USB memory | <ul style="list-style-type: none"> • Please connect USB memory again • Please insert another USB memory |
| U-14 | Can't make file because there move all file in file SHIMPO to computer is file of continuous number 999 in file SHIMPO | <ul style="list-style-type: none"> • Move all file in file SHIMPO to computer |

9.3 Memory Data File Format

oper(3rd)Memory Data

| | | |
|--|---|------|
| Open | ← | (1) |
| Date,Jul/18/2007 15:29:24 | ← | (2) |
| Model,TNX-5 | ← | (3) |
| Unit,Nm | ← | (4) |
| Data,10 | ← | (5) |
| Step,3rd | ← | (6) |
| Denominator for SD,N-1 | ← | (7) |
| .1st,2nd,3rd | | |
| Maximum,0.427,0.367,0.429 | ← | (8) |
| Minimum,0,0,0 | ← | (9) |
| Average,0.2047,0.1646,0.1839 | ← | (10) |
| Standard Deviation,0.1281,0.1187,0.1188 | ← | (11) |
| Difference,187.8,216.3,193.7 | ← | (12) |
| Upper Limit,0.1,0.2,0.3 | ← | (13) |
| Lower Limit,0.05,0.15,0.25 | ← | (14) |
| Number of High NG,8,4,1 | ← | (15) |
| Number of Low NG,1,4,8 | ← | (16) |
| Defective rate(%),90,80,90 | ← | (17) |
| No.,Date,Time,1st.,2nd.,3rd. | ← | (18) |
| ※ 1,Jul/18/2007,15:28:10,L,0.015,O,0.175,H,0.355 } 2,Jul/18/2007,15:28:47,H,0.116,L,0.145,L,0.157 } | ← | (19) |

(1)Measuring Mode:Open Memory Data(Open)Or Close Memory Data(CLOSE)

(2)Date:date of saving date in USB memory

(3)Model:TNX model

(4)Unit:torgue date unit

(5)Date number:number of torque date

(6)Open peak torque:open peak torque(1st,2nd,and3rd)in case of measuring mode is open

(7)Standard deviation:installed denominator of standard deviation

(8)Max.value:max.value of torque date

(9)Min.valne:min.value of torque date

(10)Ave.value:ave.value of torque date

(11)Denominator of standard deviation:standard deviation of torque data

(12)Variation:variation of torque data

(13)Upper limit value:installed upper limit value(note)

(14)Lower limit value:installed lower limit valae(note)

(15)Upper limit NG:number of upper limit NG of torqne data(note)

(16)lower limit NG:number of lover limit NG of torque data(nate)

(17)Fraction dafective:fraction defective of torque data(note)

(18)Data contents:data contents of torque data

No:data number

Date:measuring date of torqne data

Time:measuring time of torqne data

1st:open 1st

2nd:open 2nd


3rd:open 3rd

data:close

(19)Measuring data:every comma,data contents in each measaring data

upper/lower limit result H:hi o:go l:lo

※ 1,Jul/18/2007,15:28:10,L,0.015,O,0.175,H,0.355



(note)only upper/lower value is effective

Denominator of standard deviation, variation, and fraction defective are calculated as follows.

● In case of N-1

$$\text{denominator of standard} = \sqrt{\frac{\sum (X_i - \text{ave.value})^2}{N-1}}$$

$$\begin{aligned} \text{ave.value} &= \sum X_i / N \\ X_i &= \text{measuring data} \quad N = \text{memory data number} \end{aligned}$$

● n case of N

$$\text{denominator of standard} = \sqrt{\frac{\sum (X_i - \text{ave.value})^2}{N}}$$

$$\begin{aligned} \text{ave.value} &= \sum X_i / N \\ X_i &= \text{measuring data} \quad N = \text{memory data number} \end{aligned}$$

$$\text{variation} = (\text{denominator of standard} \times 3 / \text{ave.value}) \times 100$$


$$\text{fraction defectiver} = (\text{upper limit NG number} + \text{lower limit NG number}) / N \times 100 \quad N = \text{memory data number}$$

10. Printing

10.1 Print for statistic data

Set function f06 into print prior to printing. (11. refer to function setting)

connect option printer with outer connector of back side of body



10.2 Printing example and printing format

Open(3rd)memory data

Close memory data

| ***** OPEN DATA ***** | | | | | ***** CLOSE DATA ***** | | | |
|-----------------------|---|-------|--------|------------------------------------|------------------------|---|-------|--|
| UNIT | : | N.m | | measuring unit | UNIT | : | N.m | |
| DATA | : | 1000 | | data number | DATA | : | 14 | |
| MAX | : | 9.98 | 9.98 | max.value | MAX | : | 3.55 | |
| MIN | : | 0.00 | 0.00 | min.value | MIN | : | 0.99 | |
| AVE | : | 4.985 | 4.985 | ave.value | AVE | : | 2.779 | |
| DEV | : | 2.888 | 2.888 | stardard deviation | DEV | : | 0.617 | |
| DEN | : | n-1 | | denomination of standard deviation | DEN | : | n-1 | |
| DIS | : | 173.8 | 173.8 | variation | DIS | : | 66.6 | |
| HI LMT | : | 1.00 | 2.00 | upper limit value ※ | HI LMT | : | 4.00 | |
| LO LMT | : | 0.50 | 1.50 | lower limit value ※ | LO LMT | : | 3.50 | |
| OVER | : | 898 | 798 | over upper limit number data ※ | OVER | : | 0 | |
| UNDER | : | 51 | 151 | over lower limit number ※ | UNDER | : | 13 | |
| ERR% | : | 94.9 | 94.9 | fraction defective ※ | ERR% | : | 92.9 | |
| No. | | 1st | 2nd | | No. | | Data | |
| 1 | L | 0.00 | L 0.00 | | 1 | L | 0.99 | |
| 2 | L | 0.01 | L 0.01 | | 2 | L | 2.39 | |
| 3 | L | 0.02 | L 0.02 | | 3 | L | 2.68 | |

data
 upper/lower limit result data number ※ } 2nd:2lines
 h:hi empty;go l:lo } 3rd:3 lines
 data number

※ : Only when a high and low test is effective.

11.Function setting

11.1 Function mode

Function modes are as follows

| Item | Sub display | Setting conterds | Initial setting |
|------------------------------------|-------------|----------------------------|-----------------|
| Open peak torque | F01 | 1st, 2nd, 3rd change | 1st |
| Measuring unit | F02 | N · m, N · cm change | N · m |
| Display cycle | F03 | 1, 2, 4, 8minites change | 2 |
| A/Dfelter | F04 | 3, 20, 150 change | 3 |
| Auto powerOFF | F05 | OFF, ON (10minites) change | ON |
| Select of communication device | F06 | PC, Print change | PC |
| Change of outside output | F07 | ovEr, Hi-Lo change | ovEr |
| Denomination of standard deviation | F08 | N-1, N change | N-1 |

11.2 Operation


In power off



< Open peak torque setting >

Open peak tonque is selectable from 1 step,2step,or 3 step.

※ current setting is displayed first.




Measuring unit setting

< Measuring unit setting >

Measuring unit is selectable from N.m or N.cm.

※ current setting is displayed first




Display cycle setting

< Display cycle setting >

In measuring mode display cycle is selectable from 1 time/second, 2 times/second, 4 times/second, or 8 times/second.

※ Current setting is displayed first




ZERO RST A/D filter setting


< A/D filter setting >

Sampling cycle are as follows depending on filter response time

| Filter response time | Sampling cycle |
|----------------------|--------------------|
| 3msec | 1000numbers/second |
| 20msec | 1000numbers/second |
| 150msec | 150numbers/second |



※ Current setting is displayed first




ZERO RST Auto power off setting

< Auto power off setting >

When auto power off is effective on power on in use of battery, power becomes off automatically after 10 minutes no operation.

*No operation of key touch, outside communication, current setting is displayed first. and USB communication. Time can not be changed from 10 minutes.

※ Current setting is displayed first





ZERO RST Select of communication device

< Communication device sitting >

Set it connect voith printer or compnter


※ Cnrrnt setting is displayed first




< Setting of outside output >

Set the single of ouerweighed ortput,outside output or ortside output of compare instrument.

※ Cnrrnt setting is displayed first





※ Chift to overweighed output automatically when connecting with electric torque.



< Denominator of standard deviation >

When calculating standard deviation,you can set denominator from N-1,N.

※ Cnrrnt setting is displayed firs



12. Set determinant upper/lower limit value^{12.1}

Setting operation of determinant upper/lower limit value.

Set determinant upper/lower limit value on 4 lines that no singles, then decide decimal point. According to unit and type.

Choose 0,2,3,4...9 according through pressing recall key on 1~4 lines (press recall key to return 0 when 9)

move right by pressing mem key

Express the location of choosing unit decimal point

Set the determinate lower limit value of compare instrument by pressing o key.

Please set determinant upper limit value > determinant lower limit value.


When determinant upper limit value < determinant lower limit value, lights of Hi, go, lo shine, press open/close key

to determinant upper limit value.



< Set determinant upper limit value of open 1st of compare instrument >


※ Current setting is displayed first



Set determinant lower limit value of open 1st of compare instrument


< Set determinant lower limit value of open 1st of compare instrument >

※ Current setting is displayed first



Check out abnormality in power of in_out
Hi, Go, Lo LED Blinking

Please set through press the key as set determinant upper limit value of 1st.
 return to the setting of determinant upper limit value as check out abnormality in
 power of in_out.



12.2 Output the result of determination of compare instrument

Compare the test value(LCD indicating value)with the setting value of determinant upper limit input
 the result of compare instrument according to the.....outside.

test value>set vaky if uppe limit value,output of compare instrument is ON.

test value<set valre of lower limit value,output of compare instrument is ON.

when the setting mode of instrument is shifting output,you have to set "Hi_Lo",so as to confirm the effect of compart instrument.

13. Acquirement of data

13.1 USB communicating function

Connect the senior function digital tester to computer with accessorial USB wires,then communicating data with computer.
(Please install the tied software on the leftside of lomputer.)

13.2 Characteristic of digitorg_TNX

Bbecans of digitorg TNX ,advertising software of exced,you can get the test data of senier function data and store data from excel directly.

※ Excel は米国 MicrosoftCorporation の登録商標です。

13.3 Sequence of loaddowning the softwant.

Please search on our web,then loaddown,and land.

Double click the fice after loaddown finished.Then you can get a PDF fice"digitorg_tnx instrument mannul.Sequence for install the software,function instrument,operators,please refer to the contents.

13.4 Notes for using USB

Please don't connect USB wire without operatting for long time.

The battery will soon run out while connecting USB wires without operating it,even .

When the efficiency of the senior funtion digitad tester is OFF.


14. Convenient function

14.1 load the file set

Digitorg_TNX can make file and load from Upanel while save to TNX.

Set file include message of determinant upper/lower limit value, peak torque of open/close and (open/close) test mode.

It can operate automatically when connect with power source. If panel U is connected with mainframe. And if these is memory archives of test mode in set file, the archives will save in panel U automatically and then connect.




14.2 Warning symbol of parameter setting

It appears following symbol in parameter setting, in this condition, setting file can't be saved in TNX.

Confirm the contents indicated by symbol, then press ZERO to cancel.


| Code | Meaning | Action method |
|------|---|---|
| U-12 | No enough space in panel USB | Increase the space of panel USB |
| U-13 | Fail to visit panel USB | Connect panel USB again • Please connect another USB memory. |
| U-14 | Check out file 999 in file SHIMPO, so can't make file | • Please move all the files in a SHIMPO folder to a PC. |
| U-20 | Type of unit is not coordinate with mainframe Examine parameter singular | Reset the file according to the unit type of digitorg_TNX |

15.Operation of time setting



16. Extnal linker

16.1 Distribution of pin



• Cable (optional) 2m only for a printer in length

| Pin number | Signal names |
|------------|--|
| ① | N/A ※ 1 |
| ② | N/A ※ 1 |
| ③ | RxD (RS-232C receive data) printer → mainframe |
| ④ | Digital GND |
| ⑤ | testing connection |
| ⑥ | TxD (RS-232C Transmission data) mainframe → printer |
| ⑦ | RTS (RS-232C message requirement) printer → mainframe |
| ⑧ | Open overload /Comparator maximum outputs ※ 2 |
| ⑨ | Close overload /Comparator Lower outputs ※ 2 |
| ⑩ | Overload/Commons of comparator outputs |

※ 1 please don't connect pin ①、②

※ 2 exceeding output/you can set shift of compare instrument with the shift of function output.

16.2 Exceeding output compare instrument output start up exceeding output and compare instrument

Overload or comparator output is performed.


(Exceeding output/set shift of compare instrument with the shift of function output.)

● I/F Circuit diagram

The full open overload
/Comparator maximum outputs

Close overload
/Comparator Lower outputs

Overload
/Commons of comparator outputs



MAX capacity Voltages DC30V / Current 5mA



Please don't insert the power with exceeding the max capacity.

● Overload output

It will send signal when the mainframe is overcharge, so connect with the alarm cam protect the mainframe.

if operating overcharge in open direction, the photovoltaic coupling of PC1 will emit current. The same with PC2 when in close direction. rated torque output about 120% actually. (not include 0 setting positive value)

● Overload output

When upper limit output of compare instrument is ON, the photovoltaic coupling of PC1 will emit current.

when lower limit output of compare instrument is ON, the photovoltaic coupling of PC2 will emit current.

about details of compare instrument function, please refer to "setting operation of determinant upper limit value" (setting method and determinant conditions of determinant upper/lower limit value of compare instrument)

17.Exceptant



Please don't charge with other tool beyond accessorial AC adapter

It will lead to short circuit if connected with other tool,even arises five.

When the customer arrive near the ferronickel battery,it will discharge possibly.so please charge by AC adapter.

Connect HC adapter with its inward linker.insert socket of AC 100v.

begain to charge from socket 100V as AC adapter connected.

Concealing ferronickel battery starts to charge.

Charrge will stop automatically as the charge is fimshed.

Indicate BAT when charging.NOT indicate as it fimshed.

Charging time:at most 10 hours .Using time:8 hours for 1 time charge.

Concealing ferronickel battery will discharge outomatically when AC adapter is working.and charge outomatically when it's short.

If charge.continually,the life of ferronickel battery.

Will be shorted.so don't pull out AC adapter when it's working,so as to stave the life.

Can testing while charging

Mark"LO BAT"will flickering.when voltage of ferronickl.

Battery is not enough.now please charge.

When lo BAT is light and the voltage of batlery is low,the LCD will indicate"PWR".It'u twrn off the power compellent in about 1 minute.

18. Support

18.1 Repair.Emendation

We support service with recmpense.reward work that for keeping the definition of tester regularly.about fare and term,please ask the selley.Then about the requirment of repair,please refer to the guaranty added to product.


18.2 Pledge

Please conftrm the assuring contents is added by product guaranty.

19.Specification

| Model | | TNX-2 | TNX-5 | TNX-10 |
|---------------------------|-------------------|--|----------------------|---------------------|
| Measuring torque | | 2N · m | 5N · m | 10N · m |
| Measuring range | | 0.000 ~ ± 2.000N · m | 0.000 ~ ± 5.000N · m | 0.00 ~ ± 10.00N · m |
| Measuring unit | | N · m, N · cm exchange | | |
| Display range | | 0.000 ~ ± 2.000N · m | 0.000 ~ ± 5.000N · m | 0.00 ~ ± 10.00N · m |
| | | 0.0 ~ ± 200.0N · cm | 0.0 ~ ± 500.0N · cm | 0 ~ ± 1000N · cm |
| Display resolution | | 0.001N · m | | 0.01N · m |
| | | 0.1N · cm | | 1N · cm |
| Indicate distinguish rate | | Chuck range : φ 10 ~ φ 190mm Max quality:under 5kg when barycenter of tester is not reach the barycenter of table. | | |
| Display | Main display | 4-digit LCD display Character height 12mm | | |
| | Sub display | 3-digit LCD display Character height 7mm | | |
| | Judgment LED | Judgment LED(HI,GO,LO) | | |
| Accuracy | | ± 0.5%/F.S | | |
| Measuring mode | | Open mode,Close mode,Average mode | | |
| Display cycle | | In arerage mode,can choose 8t/s,4t/s,2t/s,1t/s. | | |
| | | Open/close mode:certoun 8t/s | | |
| Memory | Memory | Open peak test:set 1,2,3 | | |
| | Memory data num. | 1000data | | |
| | Statistic process | Average,max,min.standard deviation,test value.distrubte irregularly. | | |
| Judgment function | | Peak value of open 1st,2nd,3rd and the posibility of close...deter mination. | | |
| | | Use determinant LED to indicate determinant reslnt. | | |
| Clock functien | | There is year.month.dan saved in torque data. | | |
| Data output | USB ommuication | USB1.1 load the data by tied software | | |
| | printer | Use printer adapttd to rs232c to print storge data. Suggest compatible printer. | | |
| | USB memory | Transfer the data of panel U and storge. | | |
| Output outside | | Molelectron output,exceeding output and displace compare instrument output. | | |
| Dilation function | | Exleeding output/compare instrament output | | |
| Accessories | | USB wires.AC adapter.panel U.pin with lock(4) | | |
| Power | | Built in nickel hydride battery or AC adapter | | |
| Dimensions(mm) | | 320 × 227 × 126 | | |
| Weight | | 8 kg | | 12.5 kg |
| Usage environment | | 0 ~ 40°C | | |

20.Dimensions (mm)



MEMO

NIDEC DRIVE TECHNOLOGY CORPORATION

〈Web Page Information〉 Please scan the QR code or access the URL below.



Contact Us

<https://www.nidec.com/en/nidec-drivetechnology/inquiry/>



Sales Offices

<https://www.nidec.com/en/nidec-drivetechnology/corporate/network/sales/>

Copyright NIDEC DRIVE TECHNOLOGY CORPORATION. All Rights Reserved.

NIDEC DRIVE TECHNOLOGY CORPORATION

NIDEC SHIMPO CORPORATION change its company name to NIDEC DRIVE TECHNOLOGY CORPORATION on April 1, 2023.